

# PIC Wire & Cable

A Division of the Angelus Corporation

(262)-246-0500

Fax (262)-246-0450

PO Box 330 Sussex, WI 53089

## Termination Instructions

**T-190339**

Approved

*TVH*

Date: 10/21/13

Rev. 1 (01/21/14)

Distribution : USER

### Termination Instructions for PIC 190339 M39029 Size 8 Socket Connectors for S33141 Coax Cable

Recommended Hand Tools :	X-acto Knife, Sharp Razor, Wire Cutters
Required Cable Tools :	M22520 / 5- 01 Hex Crimp Tool M22520 / 5 - 41 Hex Crimp Die Set, cavity A (.290" hex) Soldering equipment, OR M22520 / 1 - 01 Center Contact Crimp Tool, Selector Dial @ # 6 recommended positioner: PIC 110778 (DMC # TH735), selector @ Red

Dimensions in Inches - NOT to Scale

- 1 Install ATUM 12/3 dual wall Shrink Tube x 1.5" onto the cable. Install the crimp ferrule onto the cable (Fig 1). Make Cut A @ .290" from cable end, through the jacket, braids, and foil (Fig. 1). Do not cut into dielectric. Remove jacket, wire braids, and foil.
- 2 Make Cut B @ .635" from the cable end, through the jacket only (Fig. 1). Do Not nick or cut into the wire braids. Leave this section of jacket on. Clean the exposed dielectric of debris or stray braids.
- 3 Make Cut C @ .200" from the cable end, through the dielectric (Fig 1). Do Not nick or cut into the center conductor. Remove dielectric, verify center conductor integrity.
- 4 Verify proper fit of the center contact onto the center conductor. Solder or crimp the center contact onto cable center conductor (Fig. 2). If crimping, use M22520/1-01 crimp tool, dial setting @ # 6 , with PIC 110778 positioner, selector @ Red.
- 5 Remove jacket at Cut B. Flare the wire braids away from the cable. Slit the foil shield lengthwise in three or four places around the cable and flare out the foil. Flare out the inner strip braids to expose the dielectric all the way down to the bottom (Fig. 3). The dielectric must be exposed for the full length of the strip dimension (to Cut B).
- 6 Inspect and clean dielectric and center contact as needed, using clean, dry compressed air if necessary (carefully). Inspect and clean connector body as needed.
- 7 Install the connector body over the dielectric and under the shields, until the center contact is fully seated. Avoid disturbing or deforming the dielectric.
- 8 Smooth all braids down over the rear of the connector body, covering the knurl. Trim off any excess braids past the knurled rear body, trim behind the shoulder (Fig. 4).
- 9 Pull the crimp ferrule up over the braids. Secure the body while positioning the ferrule, to avoid shifting the center conductor. Trim any stray braids at the shoulder prior to seating the ferrule against the connector body.
- 10 Verify that the connector is fully seated onto the cable. Confirm the center contact position; the end of the center contact should be  $.186" \pm .010"$  from the front end of the connector body (Fig. 5). Crimp the ferrule with M22520/5-01 crimp tool and M22520 / 5 - 41 hex die set, cavity A, .290" hex (Fig. 5).
- 11 Remove the self-extraction sleeve from the connector prior to installing dual-wall ATUM heat shrink tubing provided. Shrink the tubing, at least partially onto the shoulder (Fig. 6), to effect a seal. Trim off excess heat shrink beyond the front side of shoulder as needed, and re-install the extraction sleeve as shown (Fig. 6).

Figure 1




Figure 2




Figure 3



Figure 4




Figure 5




Figure 6



Note: Connector Length added to cable = + 1.31" nominal