	PIC Wire & Cable	Termination Instructions	T-110303	
	A Division of the Angelus Corporation	Approved : mcC	Date : 12/01/03	
	Ph (262) 246-0500 Fax (262) 246-0450 www.picwire.com		Rev. 2 : (11/13/13)	
	PO Box 330 Sussex, WI 53089	Distribution : USER	Uncontrolled Documen	
	Termination Instructions for PIC Shield (for PIC P/N E50824, E50824-X, G50824 & G53			
	Required Tooling : RJ45 Crimp Tool, PIC P/N 110288 (Sentinel P/N 900007)			
	Recommended Tooling : X-acto Knife, Sharp Razor, Wire Cutters, Eye Loupe / Magnifier			
		All Dimensions in Inches - Not to Scale		
		Step 1		
1)	Install Strain Relief Sleeve onto cable. Make Cut A (1.00" from end) through the Jacket. Remove Jacket, Braids, Foil, and white Binder tape.	Cut	A1.0	
2)	Fold each pair back, and trim off the center Spline as short as possible, using caution to avoid nicking or cutting into the wires.			
.)				
		Strain Relief Sleeve		
3)	Arrange the wires into the desired configuration, and install the wires into the Load Bar. If necessary, longer wires can be trimmed nearly as short as	Step 2		
	the shortest wire, to allow easier entry into the Load Bar. Position the Load Bar so that the front edge is 0.85" from Cut A (as shown). Trim off the end of the wires at Cut B (0.85" from Cut A, as shown). All wires should be trimmed evenly, and flush with the end of the Load Bar.		W	
			8	
4)	Make Cut C (0.30" from Cut A) through the Jacket (as shown). Do Not nick or cut into wire braids. Score the 0.30" section of Jacket lengthwise and remove the jacket only.		Trim Off	
7			Spline	
5)	With the load bar positioned at the end of the wires, install the connector	Step 3		
.,	body. Seat the wires fully into the connector, until the stranded conductors of each wire are visible through the front end of the connector body.		B Top	
			$\begin{array}{c} \mathbf{B} \\ 2 \\ 1 \\ 2 \\ 1 \\ 1 \\ -8 \end{array}$	
5)	Verify full insertion before crimping. Use of a magnifier is recommended.		ad Bar - Posso	
,	Crimp the connector using the 110288 Crimp Tool.			
7)	Slide the Strain Relief Sleeve up over metal strain relief tab, to	Trim Even 🚽	$3 \downarrow 5$ Rear View	
)	be flush with the connector body.			
		Step 4		
		Cut C	300	
			,	
		Step 5 Side Vie	X Y	
	RJ45 Pin Assignments Pin 568A Configuration 568B Configuration			
	1 White / Green White / Orange 2 Green Orange	Load Bar		
	3 White / Orange White / Green			
)	4 Blue Blue 5 White / Blue White / Blue 6 Orange Green 7 White / Brown White / Brown		└ Strain Relief tab	
	8 Brown			
		·		
	PIC Wire & Cable Termination Instruction sheets are non-controlled docu	uments. Please contact PIC Wire and Cable		