

# PIC Wire & Cable

A Division of the Angelus Corporation  
 Ph (262)-246-0500 Fax (262) 246-0450 www.picwire.com  
 PO Box 330 Sussex, WI 53089

## Termination Instructions

**T-110506-03**

Approved : *MCT*

Date : 03/06/14

Rev. 0

Distribution : USER


Uncontrolled Document

### Termination Instructions for PIC RJ45 Plug Connector P/N 110506 (for PIC Ethernet Cable P/N E13426)


Recommended Hand Tools :	X-acto Knife, Sharp Razor, Wire Cutters, Magnifier
Required Tooling :	PIC 110288 RJ45 Crimp Tool, Heat Gun

Dimensions in Inches (NOT to Scale)

- 1) Install labels (if applicable). Install ATUM 12/3 x 1.25" (larger dia.) then 8/2 x 1.0" (smaller dia.) dual wall shrink tube onto cable. Make Cut A @ .80" from cable end, through the cable jacket (Fig. 1). Do Not nick or cut into braids. Remove jacket.
- 2) Install and shrink the ATUM 8/2 x 1.0" dual wall shrink tube onto cable, starting at the end of jacket (Fig. 2). Fold braids back over ATUM, and trim off inner tape layer @ Cut A (Fig. 3). Do not nick or cut into the wire insulation; inspect wires to verify insulation integrity.
- 3) Untwist each pair, for approximately half of the stripped length, carefully straighten each wire. Align wires into desired wire configuration per work print, and install wires into the load bar (Fig. 4). Wire ends can be cut slightly shorter (up to .050") to aid entry into load bar.
- 4) Position the load bar front edge at .750" from Cut A (Fig 4). Trim off wire ends at Cut B, flush with the end of the load bar @ .750" from Cut A (Fig. 4).
- 5) Bend the RJ45 connector strain relief tab down to allow wires / load bar installation (Fig. 5a). With the load bar positioned at the end of the wires, install the connector body onto the wires / load bar. Seat all wires fully into the connector, until the stranded conductors of each wire are visible through the front end of the connector body (Fig. 5b).
- 6) Return the strain relief tab up into original position. Verify all wires are fully seated per 110506-03 Inspection Criteria (below) before crimping. Crimp the connector using 110288 RJ45 crimp tool, keeping wires fully seated. Trim off excess braids past strain relief tab (Fig. 6).
- 7) Verify all wires are fully seated per 110506-03 Inspection Criteria. Use magnifier and contrasting color background to aid in inspection.
- 8) Locate the ATUM 12/3 x 1.25" over the connector as shown (Fig. 7), and shrink onto the connector and cable, while taking care to shield the RJ45 latching tab from excessive heat. Verify full travel of the latching tab, trim back shrink tube if it impedes the latching tab (Fig. 7).



#### 110506-03 Inspection Criteria



all wires fully seated

