

# PIC Wire & Cable

A Division of the Angelus Corporation  
 Ph (262) 246-0500 Fax (262) 246-0450 www.picwire.com  
 PO Box 330 Sussex, WI 53089

## Termination Instructions

Approved : *MCS*  
 Distribution : USER

## T-110787

Date : 02/10/14  
 Rev. 0  
 Uncontrolled Document

### Termination Instructions for PIC RJ45 Shielded Plug P/N 110787 (for E50824, E50824-X, G50824 & G53824 Ethernet Cables)

Required Tooling :	PIC P/N 110288 Crimp Tool (Sentinel P/N 900007), Heat Gun
Recommended Tooling :	X-acto Knife, Sharp Razor, Wire Cutters, Locking Tab Heat Shield, Eye Loupe / Magnifier

- 1) Install ATUM shrink tube (8/2 x 0.75") onto cable.  
 Make Cut A @ 1.0" from cable end, through the cable jacket (Fig. 1). Remove jacket, braids, foil, and teflon tape. Do Not nick or cut into wire insulation. Inspect wire insulation to verify insulation integrity.
- 2) Fold each pair back, and trim off the center spline as short as possible, using caution to avoid nicking or cutting into the wires (Figs 2a, 2b). Inspect wire insulation to verify insulation integrity.
- 3) Arrange the wires into the desired configuration and install the wires into the Load Bar (Fig's 3a, 3b). If connector orientation is critical, then orient pairs prior to untwisting any pairs. If necessary, longer wires can be trimmed nearly as short as the shortest wire, to allow easier entry into the Load Bar. Position the Load Bar so that the front edge is 0.85" from Cut A (as shown). Trim off the end of the wires at Cut B (0.85" from Cut A, as shown). All wires should be trimmed evenly, and flush with the end of the Load Bar.
- 4) Make Cut C (0.30" from Cut A) through the Jacket (Fig. 4). Do Not nick or cut into wire braids. Score the 0.30" section of Jacket lengthwise and remove the jacket only.
- 5) Bend the connector body strain relief tab down (Fig. 5a) to allow wires / load bar installation. With the load bar positioned at the end of the wires, install the connector body onto the wires / load bar (Fig. 5a). Seat all wires fully into the connector, until the stranded conductors of each wire are visible through the front end of the connector body (Fig. 5b).
- 6) After verifying full insertion, ensure the exposed shield is aligned with the Metal Strain Relief as shown (Fig 6). Crimp the connector using PIC 110288 Crimp Tool.
- 7) Verify all wires are fully seated per the 110787 Inspection Criteria below (Fig.7)  
 Use a magnifier and contrasting background color to aid in inspection.
- 8) Slide up the 0.75" piece of heat shrink to the back end of the connector and shrink, ensuring heat is kept away from the latching tab which will melt or deform from too much heat. (Fig 8).

Dimensions in Inches (NOT to Scale)









Figure 7 - 110787 Inspection Criteria



Pin	568A Configuration	568B Configuration
1	White / Green	White / Orange
2	Green	Orange
3	White / Orange	White / Green
4	Blue	Blue
5	White / Blue	White / Blue
6	Orange	Green
7	White / Brown	White / Brown
8	Brown	Brown