



5000 N. Highway 251 ☎ Davis Junction, IL 61020
815.393.4600 ☎ 800.945.7135
www.SkandiaInc.com

Client:
PIC WIRE & CABLE
N63 W22619 MAIN ST.
P.O. BOX 330
SUSSEX WI 53089-0330

WO #: 110287-04
Date: 06/22/04
Test Plan #:
PO #: MONICA

Aircraft:
STOCK

S/N:
NA

60 Degree Bunsen Burner Test For Wire

FAR 25.869(a)(4) Appendix F Part I (a)(3) Amendment 25-72

Conditioning Room: Time In: 06/21/04 9:00AM Time Out: 06/22/04 10:09AM

Specimen: PIC WIRE & CABLE: WIRE, L8620TX WHITE, 20AWG, LOT #10976

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	1.0	0 No Drips
30	0.0	1.1	0 No Drips
30	0.0	1.2.	0 No Drips
Average:	0.0	1.1	0 No Drips

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed: Failed:

Signed: Carin Demus

Carin Demus