

JUL 30 1999



SKANDIA, Inc.

5181 Falcon Road • Rockford, Illinois 61109 • Phone 815/227-1611 • Fax 815/227-1920

Client:
PIC WIRE & CABLE
N63 W22619 MAIN ST.
P.O. BOX 330
SUSSEX WI 53089-0330

WO #: 36665-99
Date: 07/26/99
Test Plan #:
PO #: 009778-00

Aircraft:
STOCK

S/N:
NA

60 Degree Bunsen Burner Test For Wire

FAR 25.869 (a)(4) Appendix F Part I (a)(3)

Conditioning Room: Time In: 07/20/99

Time Out: 07/26/99

Specimen Desc.: PIC WIRE & CABLE: WIRE, 22 AWG (19 X .0058") SPC, **D5102QX**, REF PO #009778-00

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	2.0	0 No Drips
30	0.0	2.1	0 No Drips
30	0.0	2.0	0 No Drips
Average:	0.0	2.0	0 No Drips

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed:

Failed:

Signed: _____

Judy Boggs