



5000 N. Highway 251 ■ Davis Junction, IL 61020  
 815.393.4600 ■ 800.945.7135  
 www.SkandiaInc.com

Client:  
 PIC WIRE & CABLE  
 N63 W22619 MAIN ST.  
 P.O. BOX 330  
 SUSSEX WI 53089-0330

WO #: 133374-05  
 Date: 11/04/05  
 Test Plan #:  
 PO #: VERBAL

Aircraft:  
 STOCK

S/N:  
 NA

60 Degree Bunsen Burner Test For Wire

FAR 25.869(a)(4) Appendix F Part I (a)(3) Amendment 25-72

Conditioning Room: Time In: 10/03/05 9:00AM Time Out: 11/04/05 9:00AM

Specimen: PIC WIRE & CABLE: WIRE, E10422, 22AWG, LOT #11518

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	1.7	0 No Drips
30	0.0	1.5	0 No Drips
30	0.0	1.5	0 No Drips
Average:	0.0	1.6	0 No Drips

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed:  Failed:

Signed: Carin Demus  
 Carin Demus