



5000 N. Highway 251 ■ Davis Junction, IL 61020

815.393.4600 ■ 800.945.7135

www.SkandiaInc.com

JUN 18 2004

Client:
PIC WIRE & CABLE
N63 W22619 MAIN ST.
P.O. BOX 330
SUSSEX WI 53089-0330

WO #: 110003-04
Date: 06/15/04
Test Plan #:
PO #: VERBAL/MONICA

Aircraft:
SOCATA TBM700

S/N:
NA

60 Degree Bunsen Burner Test For Wire

FAR 25.869(a)(4) Appendix F Part I (a)(3) Amendment 25-72

Conditioning Room: Time In: 06/14/04 9:00AM Time Out: 06/15/04 9:00 AM

Specimen: PIC WIRE & CABLE: WIRE, T12243, 24AWG

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	1.7	0 No Drips
30	0.0	1.7	0 No Drips
30	0.0	1.6	0 No Drips
Average:	0.0	1.7	0 No Drips

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed: Failed:

Signed: Carin Demus
Carin Demus