

5000 N. Highway 251 * Davis Junction, IL 61020 815.393.4600 * 815.393.3501 (fax) www.Skandialnc.com

						Inc. WO # 248533-12 D 16978-N	
N63 V	ire & Cable /22619 Main St.			Doc ID: 60DEG-269735 Test Plan #			
P.O. Box 330				Rev			
Sussex WI 53089-0330							
		AIRCRAFT OR AIRCRAFT COMPO	VENT IDENT	IFICATION			
Make: Stock		Model:N/A	Serial: N	Serial: N/A		Tail: N/A	
Conditioning Room Data: Date In: 11/15/2012 Time In: 16:20 Date Out: 11/19/2012 Time O						me Out: 12:15	
		SPECIMEN MATE	RIALS				
Part No: E6A2824							
PIC Wire & Cable: USB Cable, White, Gauge 24, Ref. # 134056000002							
	The Annal and the state of	T Flant Time	n:	. F	n		
Set	Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)		Dub	Flame Time (seconds)	
		100001100)	(1110)	1,001		(Scooman)	
1	30	0.0		1.5		0.0	
2	30	0.0	<u> </u>	1,4		0.0	
		0.0		124			
3	30.	0.0	yda isi ya ya wa da wa a wa a wa a wa a wa a wa	1.4		0.0	
	Average:	0.0		1.4		0.0	
	60 Degree Bunsen I	Burner Test (30 seconds): Averag	e Flame Ti	ime may not exc	ceed 30 se	econds.	
A		ot exceed 3 inches. Average Drip					
Comments:							
	A CONTRACTOR OF THE CONTRACTOR			X	Passe	d Failed	
CERTIFICATION: I certify that after testing these specimens, the above results were obtained in accordance with the							
procedures and equipment specified by Code of Federal Regulations Title 14 Part 25, revised as of January 1, 2004 and							
the Aircraft Materials Fire test Handbook dated April, 2000.							
Jennifer Paluzzi -FAA DER ALM N. D. Hallani 11/19/2012							
WITNESS						DATE	