



SKANDIA, Inc.

5181 Falcon Road • Rockford, Illinois 61109 • Phone 815/227-1611 • Fax 815/227-1920

Client:
PIC WIRE & CABLE
N63 W22619 MAIN ST.
P.O. BOX 330
SUSSEX WI 53089-0330

Aircraft:
DORNIER 428

WO #: 48836-00
Date: 06/07/00
Test Plan #:
PO #:

S/N:

60 Degree Bunsen Burner Test For Wire
FAR 25.869 (a)(4) Appendix F Part I (a)(3)

Conditioning Room: Time In: 06/01/00

Time Out: 06/07/00

Specimen Desc.: PIC WIRE & CABLE: ASCB* DATA BUS CABLE, 24AWG, PART #T69654

| Flame Application (seconds) | Flame Time (seconds) | Burn Length (inches) | Drip Flame Time (Seconds) |
|-----------------------------|----------------------|----------------------|---------------------------|
| 30 | 0.0 | 1.0 | 0 No Drips |
| 30 | 0.0 | 1.1 | 0 No Drips |
| 30 | 0.0 | 1.1 | 0 No Drips |
| Average: | 0.0 | 1.1 | 0 No Drips |

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed: Failed:

Signed: Carin Demus
Carin Demus