



SKANDIA

5000 N. Highway 251 ■ Davis Junction, IL 61020
815.393.4600 ■ 800.945.7135
www.SkandiaInc.com

JAN 24 2007

Client: Pic Wire & Cable
N63 W22619 Main St.
P.o. Box 330
Sussex WI 53089-0330

WO #: 155395-07
Date: 01/22/07
Test Plan #:
PO #: VERBAL

Aircraft:
STOCK

S/N:
N/A

60 Degree Bunsen Burner Test For Wire

14 CFR Part 25.869 (a)(4) Amdt 25-113 Appendix F Part I (a)(3)

Conditioning Room: Time In: 01/19/07

Time Out: 01/22/07

Specimen: PIC WIRE & CABLE: CONDUCTOR CABLE, 24 AWG, PART #E40424, LOT #13310

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	1.6	0 No Drips
30	0.0	1.7	0 No Drips
30	0.0	1.8	0 No Drips
Average:	0.0	1.7	0 No Drips

Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed: Failed:

Signed: Carin Demus
Carin Demus