



# SKANDIA

5000 N. Highway 251 ■ Davis Junction, IL 61020

815.393.4600 ■ 800.945.7135

www.SkandiaInc.com

JAN 24 2007

Client: Pic Wire & Cable  
N63 W22619 Main St.  
P.o. Box 330  
Sussex WI 53089-0330

WO #: 155395-07  
Date: 01/22/07  
Test Plan #:  
PO #: VERBAL

Aircraft:  
STOCK

S/N:  
N/A

### 60 Degree Bunsen Burner Test For Wire

14 CFR Part 25.869 (a)(4) Amdt 25-113 Appendix F Part I (a)(3)

Conditioning Room: Time In: 01/19/07

Time Out: 01/22/07

Specimen: PIC WIRE & CABLE: CONDUCTOR CABLE, 24 AWG, PART #E40424, LOT #13310

Flame Application (seconds)	Flame Time (seconds)	Burn Length (inches)	Drip Flame Time (Seconds)
30	0.0	1.6	0 No Drips
30	0.0	1.7	0 No Drips
30	0.0	1.8	0 No Drips
Average:	0.0	1.7	0 No Drips

#### Comments:

60 Degree Bunsen Burner Test (30 sec.): Average Flame Time may not exceed 30 sec. Average Burn Length may not exceed 3". Average Drip Flame Time may not exceed 3 sec. after falling.

Passed:  Failed:

Signed: Carin Demus  
Carin Demus